



# RF Explorer<sup>®</sup> SERIES

**Spectrum Analyzer ProAudio Firmware Version 3.08**

## **Cumulative Release Notes**

RF Explorer is an affordable Handheld Spectrum Analyzer with a growing list of features.

*This little powerful unit is the tool you need  
to reduce the implementation time and cost  
of your next wireless project.*

*This Release Notes document is complementary to the RF Explorer User Manual, [available online](#).*



*Please consider the environment before printing this document.*

## Firmware Upgrade Instructions

This firmware is only compatible with RF Explorer ProAudio model.

To upload this firmware, you must use the Uploader tool included in this software package. Firmware upgrade is a safe, simple process that can be repeated many times if something goes wrong.

You can update firmware using MacOS X operating system.

For more details on how to upload firmware into your device, please visit online guide:

[www.rf-explorer.com/upgrade](http://www.rf-explorer.com/upgrade)

Firmware upgrade troubleshooting:

Note: If the unit completes upgrade and remains on screen with "S/N Init..." message, please wait a few seconds to complete the upgrade.

Check in the CONFIG MENU of the RF Explorer device it is configured for 500Kbps or 2400bps same as you select in Firmware Update tool.

If fails after a couple of attempts, then please contact us at [contact@rf-explorer.com](mailto:contact@rf-explorer.com) and provide us with:

- File RFExplorer\_Uploader.log available in the <My Documents> folder of your computer.
- Operating System version and confirmation you are connecting directly to USB port on your computer, not an intermediate USB hub.

If the problem persist, you can overcome this step by pressing ENTER when a small message shows up with <Press ENTER to Stop> next to "S/N Init..." on screen.

## Version 3.08

Release date: CET Feb 04, 2019

### Enhancements:

- Improved High Resolution mode scan speed.
- Added flexible command mode support to improve response in High Resolution mode.

## Disclaimer

RF Explorer is a registered trademark.

This firmware is copyrighted by (C) Ariel Rocholl, 2010-2021, licensed to RF Venue Inc.

For more info on RF Explorer, please visit [www.rf-explorer.com](http://www.rf-explorer.com)

For more info on ProAudio model, please visit [www.rfvenue.com](http://www.rfvenue.com)

For instructions to upload this new firmware in your RF Explorer unit, please visit online documentation at [www.rf-explorer.com/upgrade](http://www.rf-explorer.com/upgrade) .

You agree that the firmware is provided as-is, without warranty of any kind (either express or implied). Accordingly, we make no warranties, representations or guarantees, either express or implied, and disclaims all such warranties, representations or guarantees, including, without limitation, the implied warranties of merchantability and fitness for any particular purpose, as to: (a) the functionality or non-infringement of program, any modification, a combined work or an aggregate work; or (b) the results of any project undertaken using the program, any modification, a combined work or an aggregate work. In no event shall the contributors be liable for any direct, indirect, incidental, special, exemplary, consequential or any other damages (including, but not limited to, procurement of substitute goods or services; loss of use, data, or profits; or business interruption) however caused and on any theory of liability, whether in contract, strict liability, or tort (including negligence or otherwise) arising in any way out of the use of the program, even if advised of the possibility of such damages. You hereby waive any claims for damages of any kind against contributors which may result from your use of the firmware.